

Volvo Trucks North America, Inc.

RECEIVE

90 007 25 Mt 9: 37

DEFECTS DIVESTIGATION

October 21, 1999

<u>CERTIFIED MAIL - RETURN RECEIPT</u>

991 296.001 (1)

Associate Administrator for Enforcement National Highway Traffic Safety Administration 400 Seventh Street, S.W. Washington, DC 20590

Subject: Continental General Tire Recall

In accordance with the requirements of 49 CFR Part 573, Volvo Trucks North America, Inc. submits the following information.

Volvo Trucks North America on October 14, 1999 received a recall notification from Continental General Tire concerning a defect in certain General S380A Load Range G tires. See exhibit "A".

Continental General Tire stated that "the use of these tires may result in separation occurring in the tread area. These separations may progress circumferentially within the tire resulting in a complete tire failure".

Continental General Tire requested Volvo Trucks to supply a listing of vehicles on which the suspect tires were installed so that they can conduct a recall.

Based on the information provided by Continental General Tire, a total of twenty (20) Volvo VNL64T class 8 vehicles built between October 10, 1998 and February 19, 1999 were identified as potentially having been built with the suspect tires.

Per discussions with Continental General Tire it is Volvo Trucks understanding that Continental General Tire will be conducting all aspects of the recall according to the requirements of 49 CFR Parts 573 and Part 577. Based on this understanding, Volvo Trucks on October 20, 1999 provided listings identifying the vehicles and vehicle owners that will be affected by the subject recall. See exhibit "B".

Best Regards

Charles D. Powell

Recall Administrator

C.D. Prwell



LEGAL DEPT. 0CT 1 4 1999

991-2**96.**001 (12)

VOLVO GM HBAVY TRUCK CORP PO BOX 1126 DUBLIN,VA -24084 USA

September 28, 1999

Continental General Tire,Inc. Consumers



PRODUCT RECALL - URGENT - READ IMMEDIATELY

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle safety Act.

Continental general Tire, Inc. has determined that a defect, which relates to motor vehicle safety, exists in the following described tires:

GENERAL S380A LOAD RANGE G
PRODUCT CODE -- 0205028
SERIAL PRODUCTION -- FROM WEEK 48 OF 1998
THROUGH TO AND INCLUDING WEEK 8 OF 1999
EXCLUSIVELY FROM CURING PRESS CAVITIES
30A AND 30B, TOTAL PRODUCTION 4750 UNITS
(0.18% OF ANNUAL PRODUCTION)

DOT SERIAL AND CURING PRESS CAVITY NUMBERS: SEE ATTACHED LIST

Although not all of these tires are defective, we have identified to date 0.36% of tires produced from the subject period and presses. However, in the interest of our customers' total safety, we are instituting this voluntary recall of all affected tires.

The use and operation of these tires may result in separation occurring in the tread area. These separations may progress circumferentially within the tire resulting in a complete tire failure. If a tire failure does occur, vehicle loss of control could result.

As the separations within the tire progress, there may be a warning to the operator of the vehicle through vibrations and/or thumping sensations. If felt or heard, the vehicle must be stopped and the tires inspected. If these warnings are not heeded, tire failure may occur.

You should immediately bring your vehicle to the nearest authorized Continental General Tire Inc., Dealer (list to be provided) for inspection of your tires. There will be no charge for the replacement tire, nor will there be any charge for installation if done within sixty (60) days of receipt of this notification.

If your account has been serviced by a specific Dealer of Continental General Tire Inc. products, please contact them within the 60-day period and arrangements will be made to examine the tires at your premises. If you need assistance, please call our Field Engineering Hotline 1-800-726-7113.

We believe that the exchange and servicing will take thirty (30) minutes per tire.

In the event that the tire is returned to us after the expiration of sixty (60) days from the receipt of this notification, we will cause a pro-rate adjustment based upon the application of our limited warranty adjustment policy.

In the event you believe this remedy is inadequate, you may submit a complaint to the Administrator, National Highway Traffic Safety Administrator (NHTSA), 400 Seventh Street, SW, Washington, DC 20590 or call the free Auto Safety Hotline, 1-800-424-9393 (Washington, DC (202) 366-0123).

Sincerely yours,

Roger A. Stansble

National Field Engineering Manager-Commercial Division

Continental General Tire Inc.


Royer A. Stanke


Attachments

Serial and curing press chamber numbers Charlotte Office address Mount Vernon tire return address

295/75R22.5 \$380A DOT SERIAL & CURING PRESS CAVITY NUMBERS

A3371E5 488 PRESS CAVITY # 30A or 30B A3371E5 498 PRESS CAVITY # 30A or 30B A3371E5 508 PRESS CAVITY # 30A or 30B PRESS CAVITY #30A or 30B A3371E5 518 A3371E5 528 PRESS CAVITY # 30A or 30B A3371E5 019 PRESS CAVITY # 30A or 30B A3371E5 029 PRESS CAVITY # 30A or 30B A3371E5 039 PRESS CAVITY #30A or 30B A3371E5 049 PRESS CAVITY # 30A or 30B PRESS CAVITY # 30A or 30B A3371E5 059 A3371E5 069 PRESS CAVITY # 30A or 30B A3371E5 079 PRESS CAVITY # 30A or 30B A3371E5 089 PRESS CAVITY # 30A or 30B





COMMERCIAL FIELD ENGINEERING OFFICE

CONTINENTAL GENERAL TIRE INC. Hotline 1-800-726-7113 1800 CONTINENTAL BLVD., Telephone (704) 583-8831 CHARLOTTE, NC 28273 Telefax (704) 583-8737

Mt. VERNON - FACTORY - (RETURN of TIRES) CONTINENTAL GENERAL TIRE INC. Telephone (618) 246-2622 11525 North Illinois Hwy 142, Telefax (618) 246-2609 Mt. VERNON, IL 62864

Voivo Trucks North America, Inc.

October 20, 1999

EXHIBIT B

Federal Express - Over Night

Mr. Douglas Neves Continental General Tire, Inc. 1800 Continental Blvd. Charlotte, NC 28273

Subject: Continental General Tire Recall

Dear Mr. Neves;

In response to Continental General Tire's recall notice received on October 14, 1999, Volvo Trucks North America, Inc. submits the vehicle and owner information required to notify the affected vehicle owners of the subject recall. The enclosed information is to be used to notify the affected Volvo owners of the subject recall and for no other purposes.

It is Volvo Trucks North America's understanding that Continental General Tire will be conducting the subject recall per the requirements of Federal Code of Regulations (CFR) Title 49 – Transportation Part 573 Notification, and Part 577 Defect and Non-Compliance Reports for the affected Volvo model vehicles.

Based on the information provided by Continental General, Volvo Trucks warranty records identified 20 vehicles, which were built with the suspect S380A tires.

The enclosed listings are broken down into the following categories.

Section 1 – Vehicle Selection Parameters:

This section identifies the tire part number, and dates used to select the affected vehicles.

Section 2 - Search List of Vehicles Selected:

This section identifies the vehicles selected by the tire part number and is in Vehicle Identification Number (VIN) order.

VOLVO

Mr. Douglas Neves Page Two October 20, 1999

Section 3 – USA Owner Vehicles:

This section identifies the USA vehicles by owner name, address, and VIN of the vehicle. The section is in alpha order.

Vehicle Inquiry:

This page identifies one vehicle that the first report did not list. Serial number 777212 should be included in your recall.

The first group total is 19 vehicles with the additional one vehicle the total Volvo VNL64T vehicles affected by the recall is 20 vehicles.

Should you have any questions, please contact me at (336) 393-2233.

Very Truly Yours,

Charles D. Powell Recall Administrator

C.K. Provell

Enclosures: 4